Regency
the first name in solid state

PROFESSIONAL 2 WAY action radio

DATE 12/2/82

# SSC Service Bulletin

no. 82-286

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES AND SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: RAP-200/DPC-221/RTC-2 WHEN USED TOGETHER

SYMPTOM: SOME TELEPHONE SYSTEMS WILL NOT ACKNOWLEDGE THE DPC-221 PULSE DIALER WHEN USED IN CONJUNCTION WITH THE RTC-2 VOICE COUPLER

SOLUTION:

1. Remove violet wires from W and X of top edge cord connector in the RAP-200 and solder them together.
2. Remove wire from the RAP-200 rear terminal block lug number 23 and solder to top edge cord connector Pin X.
3. Add jumper from top edge cord connector Pin W to the rear of the terminal block lug 23.

TECHNICAL SERVICE DEPARTMENT
REGENCY COMMUNICATIONS, INC.